



1/6



PRIOR ART



FIG. 1





PRIOR ART

FIG. 2

2/6

**FIG. 3****FIG. 4**

3/6

**FIG. 4A****FIG. 4B**

**REPLACEMENT SHEET**HP DOCKET # 200315712-1  
IMPROVED HINGE FOR ELECTRONIC DEVICE  
HOMER, ET AL.

CONTACT: DAVID W. BOYD (970) 898-4475

4/6




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D





FIG. 5E

**NEW SHEET**


HOMER, ET AL.

HP DOCKET # 200315712-1  
IMPROVED HINGE FOR ELECTRONIC DEVICE  
CONTACT: DAVID W. BOYD (970) 898-4475

**5/6**



**FIG. 6**




**FIG. 7**

**NEW SHEET**


HOMER, ET AL.

HP DOCKET # 200315712-1  
IMPROVED HINGE FOR ELECTRONIC DEVICE  
CONTACT: DAVID W. BOYD (970) 898-4475

**6/6**



**FIG. 8**



**FIG. 9**